

Channel Protection and Storm Flow Improvements



Example: Channel Protection



Texas-Crossing Improvements and Erosion protection

Several drainage drop-structures along Timbers Creek west of Fox Sparrow Rd. were repaired to protect the channel and improve storm flows. The improvements included the “Texas-Crossing” south of Pinon Jay Rd. where storm water had undermined the path connecting to the neighborhood. **ONGOING**

August, 2014